



Risk Assessment for Mobile Protecta Cube

Date

Completed By

ZERO DUST

ZERO DAMAGE

ZERO DEFECTS

19.11.2021

Protecta Group

Step/Process	Hazzard Identification	Risk controls + Precautions
Moving/Relocating the Cube	Risk of injury to personnel in vicinity + adjacent structures + equipment	Ensure wheel castor brakes are released. Ensure visibility - use a spotter. This operation is preferably carried out with 2 people.
Parking the Cube for use	Risk to personnel and adjacent structures + equipment if the cube rolls	Ensure the 4 castor brakes are engaged
Raising + Lowering the plastic sides	Damage to the cube	Raise the rear poles 200-300mm and then the front poles – repeat the process until the foam top rail is lightly compressed against the ceiling.
Working off a platform ladder in the Cube	Falling risks and dropping tools. Injury to personnel and damage to the cube.	Ensure ladder is positioned correctly and tools are controlled to prevent dropping
Entry + Exiting Cube	Head injury due to low door head height and tripping on the step.	Maintain awareness of door head height and the step at the doorway.
Ventilation	Risk to worker overheating	Maintain hydration. Ensure Hepa unit is operational; and turned on.
Using HEPA	Filter clogging	Routine checking and replacement of filters as required.
Use of electrical tools	Electrocution	Test + tag tools and electrical as required. Do not use damaged equipment.

NB: - It is recommended that a site specific risk assessment is carried out by the owner/user.

SYDNEY (HEAD OFFICE) 13 Rachael Cl, Silverwater NSW, 2128 (02) 9334 2999 sales@protectagroup.com.au Warehouse: 30 Fariola St, Silverwater NSW, 2128 MELBOURNE 3 Saligna Drive, Tullamarine VIC, 3043 (03) 9002 2899 <u>VICsales@protectagroup.com.au</u> BRISBANE 99 Holt St (Cnr Chapman PI), Eagle Farm QLD, 4009 (07) 3363 3799 <u>QLDsales@protectagroup.com.au</u> PERTH 51 Wittenberg Dr, Canning Vale WA, 6155 (08) 6269 6999 WAsales@protectagroup.com.au